ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0864, W1301, W0872, W0856	NA	Cavery layout
Segment No.	**Total Length (m)**	
6/C-W0864/S045248	36.95	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	12.84	77.608666	13.051463	77.608650	13.051348	Cavery layout	1st Cross
2	12.88	77.608733	13.051852	77.608714	13.051737	Cavery layout	2nd cross
3	11.23	77.608781	13.052158	77.608760	13.052058	Cavery layout	3rd Cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of culverts Dasarahalli surroundings area in ward no. 6 Byatarayanapura sub division	500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	culverts
Tender	**Work Details**	**Job No. / Work Code**
Tender	culverts	006-16-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/45/2016-17	27/05/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/05/2016	27/05/2017	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
NAveen Chandra		0.00
Phone No.	**E-Mail ID**	
9980382153		

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0864, W1301, W0872, W0856

AE

Field Inspection Details

Number of Trees	Any Other Information	Name
0		krishnappa
Date of Inspection	**Remarks**	
20/06/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	25/06/2018	20/07/2018	As proposed
SE	Vasu K M	22/06/2018	20/07/2018	Verified
EE	Yerappareddy	20/06/2018	20/07/2018	Verified
AEE	J.N.Lokesh	20/06/2018	20/07/2018	Verified
AE	Krishnappa	20/06/2018	20/07/2018	Mobile verification is done
AE	Krishnappa	20/06/2018	20/07/2018	Forwarded

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0864, W1301, W0872, W0856

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0577	NA	Dasarahalli
Segment No.	**Total Length (m)**	
6/S-W0577/S044201	10.55	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	10.55	77.610447	13.057336	77.610463	13.057242	Kempegowda circle	14th Cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of culverts Dasarahalli surrounding area in ward no. 6 Byatarayanapura sub division.	500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	culvert
Tender	**Work Details**	**Job No. / Work Code**
Tender		006-16-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/45/2016-17	27/05/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/05/2016	27/05/2017	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
NAveen Chandra		0.00
Phone No.	**E-Mail ID**	
9980382153		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		krishnappa
Date of Inspection	**Remarks**	
20/06/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	25/06/2018	20/07/2018	As proposed
SE	Vasu K M	22/06/2018	20/07/2018	Verified
EE	Yarappareddy	20/06/2018	20/07/2018	Verified
AEE	J.N. Lokesh	20/06/2018	20/07/2018	Verified
AE	Krishnappa	20/06/2018	20/07/2018	Mobile verification is done
AE	Krishnappa	20/06/2018	20/07/2018	Forwarded